



SWING MOORING INSPECTION

Mooring Buoy No: LBYC / RPNYC

Mooring Owners Name: Lowry Bay Yacht Club

Mooring Owners Address: Lowry Bay Yacht Club

Mooring Area: Somes Island East

Inspection Date: 5th February 2020

Inspection Time: 1230

Water Depth: 8.6m

DETAILS OF MOORING

Type of Block: Concrete **Block Dimensions:** 2 ton block.

Block Eye - Original size: >30mm

Worn to: >30mm

The attachment of the eye to the block could not be measured although it appeared solid

Shackle - Original size: 30mm

Worn to: 24mm

Mousing: Plastic

Ground Chain - Original size: >30mm

Worn to: >30mm

Shackle - Original size: 30mm

Worn to: 30mm

Mousing: Plastic

Top Chain - Original size: 25mm

Worn to: 24mm

Shackle - Original size: 30mm

Worn to: 30mm

Mousing: Plastic

Rope and Subsurface float – Size – 32mm Description: 2 lengths of rope. The bottom piece is choked onto the shackle and has the subsurface float on it. The upper length is choked to the lower rope above the SS float. Spliced soft eye at the top

Buoy – Orange Pole Buoy marked with LBYC and RPNYC

COMMENTS:

This is mooring is in good condition.

This is to certify that I have inspected this mooring, and the information noted above is a true and accurate reflection of the mooring at the time of inspection.

Name of Inspector: Murray Wilson

Wilson Underwater Services Ltd.

www.wilsonunderwater.com

Phone +64 21 440 420

