



---

## SWING MOORING INSPECTION

**Mooring Buoy No:** *LBYC / RPNYC*

**Mooring Owners Name:** *Lowry Bay Yacht Club*

**Mooring Owners Address:** *Lowry Bay Yacht Club*

**Mooring Area:** *Somes Island (West)*

**Inspection Date:** *5<sup>th</sup> February 2020*

**Inspection Time:** 1100

**Water Depth:** *6.9m*

### DETAILS OF MOORING

**Type of Block:** Concrete **Block Dimensions:** 5 ton block.

**Ground Chain - Original size:** >40mm

**Worn to:** >40mm

The Ground chain is cast into the block

**Shackle - Original size:** 32mm

**Worn to:** 32mm

**Mousing:** Plastic

**Top Chain - Original size:** 20mm

**Worn to:** 20mm

**Length:** 6.0m

**Shackle - Original size:** 32mm

**Worn to:** 32mm

**Mousing:** Plastic

**Rope and Subsurface float – Size – 32mm Description:** 2 lengths of rope. The bottom piece is choked onto the shackle and has the subsurface float on it. The upper length is choked to the lower rope above the SS float. Spliced soft eye at the top

**Buoy – Orange Pole Buoy marked with LBYC and RPNYC**

### COMMENTS:

This is mooring is in good condition.

This is to certify that I have inspected this mooring, and the information noted above is a true and accurate reflection of the mooring at the time of inspection.

**Name of Inspector:** Murray Wilson